

## FITNESS CERTIFICATE

To be filled by the Inspecting officer (Assistant Engineer)

(Re:G.O.Ms.20/70/PWD dt.23/01/1970)

- |  |   |
|--|---|
| 1.Name of the officer  | - Jinu Aravind  |
| 2.Name of the school/Anganvadi   | -Bishop Pereira Memorial School,<br>Karamoodu   |
| 3.Location with name of Education District/Sub district  | -Kaniyapuram  |
| 4. Claasification of building as specified in column 4 of the application for fitness certificate and size | -76.15 x 8.70x3.60 (G+2 Rcc Bldg)<br>-10.39x14.36x3.60(G+1 Rcc Bldg)<br>-12.66x13.80x3.60(G+1 Rcc Bldg)<br>-52.73x8.72x3.60(G+1 Rcc Bldg) |
| 5.Period for which the certificate is issued   | - 2024-25   |
| 6.Nature of defects if any   |   |
| a)Foundation and basement  | -nil  |
| b)Super structure  | -nil  |
| c)Doors and windows  | -nil  |
| d)Wood work wrought and put up   | -nil  |
| e)Roof   | -nil  |
| f)Flooring   | -nil  |
| g)Miscellaneous(Crack etc.)  | - nil   |
| 7.Any major defects noticed which will render the building unsafe in any manner                            | -No   |
| 8.Whether maintenance work have been done properly   | -yes  |
| 9.Whether the structure is sound or not for conducting classes   | -Building is structurally sound for conducting classes under normal wind and weather condition  |

Note:-1.The stability of the structure should be examined also with reference to location ,altitude,intensity of wind ,exposure of flood etc.2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

**CERTIFICATE**

Certified that the school building was inspected by me on **26/06/2024** and found to be fit to conduct classes, for the period **2024-25** for the reasons stated above.

Place-Kaniyapuram

Date -28/06/2024

